

Latest Firmware for the HP 54600 Series Instruments

Special Notes for 54600 Series:

- The old "A" scopes do not support the 54652B and 54659B modules. The new 54645A and 54645D do support the 54652B and 54659B modules as do all the "B" scopes.
- 1.2 code is required in the "B" scopes to run 54652B and 54659B.
- 2.2 code is required in the "A" scopes to support FFT in 54657A/58A.
- All B model scopes support the FFT in 54657A/58A.
- 54652B and 54659B do not contain ROMs, the rest of the modules do.
- Old "A" model scopes do care what ROMs are in the modules. If upgrading an old "A" model scope, you must also upgrade the module.
- "B" model scopes do not care what ROMs are in the modules because the code for running modules is in the scope itself.

54600A/01A/02A/10A Oscilloscopes

Model Number	Upgrade Kit	ROM Number	Instructions	Revision
54600A/01A/02A	54601-68702	54600-80013	5961-1902	3.2
54610A	None	54610-80010	None	3.1

54600B/01B/02B/03B/10B Oscilloscopes

Model Number	Upgrade Kit	ROM Number	Instructions	Revision
54600B/01B/02B/03B	54601-68704	54600-80015 17	54601-92000	4.31 1.35
54610B	54610-68704	54610-80023 54610-80024	54610-92000	1.31

54615B/16B/16C Oscilloscopes

Model Number	Upgrade Kit	ROM Number	Instructions	Revision
54615B/16B/16C	54615-68704	54615-80012 54615-80013	54615-92002	2.3

54645A/D Oscilloscopes

Model Number	Upgrade Kit	ROM Number	Instructions	Revision
54645A/45D	54645-68702	54645-80009 54645-80010	54645-92002	2.0 ⁰⁵ 3

54620A/20C Logic Analyzers

Model Number	Upgrade Kit	ROM Number	Instructions	Revision
54620A	54620-68704	54620-80015	54620-92001	A.01.30
54620C	none yet	54620-80014	one release	A.01.30

54650A/51A/52A/52B/55A/56A/57A/58A/59B Modules

Model Number	Upgrade Kit	ROM Number	Instructions	Revision
54650A/51A/52A	54650-68704	54650-80008	5090-4815	3.0
54655A/56A	54655-68702	54656-80004	5090-4886	3.0
54657A/58A	54657-68702	54658-80006	5090-4814	3.0